

MEASUREMENT POINTS(IN CMS)	tol+-	NB	0-6 M	6 - 12 M	18 M	24 M	HOW TO MEASURE
FULL LENGTH AT SIDE SEAM		A	10	10.5	11.5	12.5	13
WAIST RELAXED (WITH ROUND ELASTIC)		B	18	20	20.5	21.5	23
WAIST BAND ELASTIC HEIGHT		D	1.5	1.5	1.5	1.5	1.5
FRONT & BACK TOTAL HEIGHT		E	20.5	21.5	23	24.5	25.5
CROTCH WIDTH		G	11.5	13	13.5	14	14
HIPS		H	29	30	32	35	36.5
LEG OPEN			10	11	12	12.5	13
LEG ELASTIC HEIGHT		I	1	1	1	1	1

